

# Cendor MOPU Export Riser Repair

**Client:** Petrofac

**Year:** 2012

**Location:** Malaysia


## Description

Replacement of 6" export riser section.  
Cendor MOPU. 70m water depth.

## Antares Scope

Project management and engineering:

- Mobilise replacement riser section
- Mobilise DSV with installation spread
- Removal of damaged section and installation of new section



## Project Profile